

**EXHIBIT A**

LPA RX 851 WD

Page 1 of 3

Rev. 01/21

Ver. Date 01/29/2021

PID 110376

**PARCEL 16-WD  
FRA-161-12.83  
ALL RIGHT, TITLE AND INTEREST IN FEE SIMPLE  
IN THE FOLLOWING DESCRIBED PROPERTY  
WITHOUT LIMITATION OF EXISTING ACCESS RIGHTS  
IN THE NAME AND FOR THE USE OF THE  
CITY OF COLUMBUS, OHIO, A MUNICIPAL CORPORATION**

Grantor/Owner, for himself and his heirs, executors, administrators, successors and assigns, reserves all existing rights of ingress and egress to and from any residual area (as used herein, the expression "Grantor/Owner" includes the plural, and words in the masculine include the feminine or neuter).

---

**[Surveyor's description of the premises follows]**

---

Situated in the State of Ohio, County of Franklin, City of Columbus, lying in southeast Quarter Township 4, Township 2 North, Range 18 West, of the United-States Military Lands, part of Lot 2 of the Scioto Land Company Partition as recorded in Deed Book A, Page 194 (destroyed by fire) and re-recorded in Deed Book A, Page 21, part of Lots 9 and 49 of Sharon Acres as recorded in Plat Book 20, Page 1, and being part of a 1.430 acre tract conveyed to Lukie Arkansas Ohio, LLC, a Delaware limited liability company (hereinafter referred to as "Grantor") by deed of record in Instrument Number 201910040131677 (Franklin County Parcel Number 010-147408-00) (all documents referenced herein are from the Franklin County Recorder's Office), and being more particularly described as follows:

**BEGIN FOR REFERENCE** at the centerline right-of-way intersection of East Dublin Granville Road (SR 161), (Station 679+77.56) and Maple Canyon Avenue (Station 50+00.00), being referenced by a found iron pin in concrete at centerline Station 685+80.83, (East Dublin Granville Road (SR 161)), 8.31 feet left, which bearing South 85°26' 09" East a distance of 603.59 feet;

Thence North 03° 38' 29" East a distance of 150.02 feet along centerline of Maple Canyon Avenue (width varies) to a point at centerline Station 51+50.02;

## EXHIBIT A

Page 2 of 3

LPA RX 851 WD

Rev. 01/21

Thence North 86° 21' 31" West a distance of 25.00 feet, leaving the centerline across Maple Canyon Avenue to a 5/8" iron pin found at the Grantor's southeast corner and the intersection of the northerly right-of-way line of East Dublin Granville Road (SR 161) (width varies), and the westerly right-of-way line of Maple Canyon Avenue (width varies), 25.00 feet left of centerline station 51+50.02, and the **TRUE POINT OF BEGINNING** for the parcel herein described;

Thence South 89° 51' 35" West a distance of 20.16 feet along the southerly line of the Grantor and the northerly right-of-way line of East Dublin Granville Road (SR 161), acquired by the State of Ohio by deed of record in Deed Book 3044, Page 127, to an iron pin set 45.12 feet left of centerline station 51+48.69;

Thence leaving the Grantor's southerly line and the northerly right-of-way line of East Dublin Granville Road (SR 161) on the following courses across the Grantor's 1.430 acre tract;

1. North 36° 58' 52" East a distance of 18.41 feet to an iron pin set 35.00 feet left of centerline station 51+64.07;
2. North 03° 38' 29" East a distance of 172.52 feet to an iron pin set 35.00 feet left of centerline station 53+36.60;
3. North 07° 25' 50" East a distance of 45.39 feet to an iron pin set on the line common to the Grantor and a 2.632 acre tract conveyed to TMA Maple, LLC, an Ohio limited liability company by deed of record in Instrument Number 200808140124379, 32.00 feet left of centerline station 53+81.89;

Thence South 86° 25' 05" East a distance of 7.00 feet along the line common to the Grantor and said 2.632 acre tract to a point on the westerly right-of-way line of Maple Canyon Avenue 25.00 feet left of centerline station 53+81.90;

Thence South 03° 38' 29" West a distance of 231.88 feet along the Grantor's easterly line and the westerly right-of-way line of Maple Canyon Avenue to the **TRUE POINT OF BEGINNING**, containing 0.053 acres, more or less, being subject to all easements, restrictions, and right-of-way of record.

This description was prepared by Robert J. Sands, Ohio Professional Survey Number 8053, and is based on a survey conducted by DLZ Ohio, Inc. in 2020 under his direct supervision.

**EXHIBIT A**

Page 3 of 3

LPA RX 851 WD

Rev. 01/21

The bearings for this description are based on the Ohio State Plane Coordinate System, South Zone, and reference the North American Datum of 1983 and the 2007 adjustment (NAD83(2007)), with the bearing of Maple Canyon Avenue being North 3°38'29" E.

Where described, iron pins set are 5/8 inch rebar, 30 inches long, with yellow caps stamped "DLZ OHIO INC."

All station and offsets referenced in this description are from the right-of-way centerline of Maple Canyon Avenue as described in the plan known as "IMPROVEMENTS OF SR 161/I71" on file with the Ohio Department of Transportation and the City of Columbus.

---

Robert J. Sands  
Professional Surveyor No. 8053

---

Date