

Vendor account	Line number	Product name	Quantity	Unit price	Total
6876					\$ 24,499.88
6876	10	Peerless Service	1	\$ 1,950.00	\$ 1,950.00
6876	20	Peerless Service	1	\$ 1,950.00	\$ 1,950.00
6876	30	Inboard Bearing	2	\$ 249.00	\$ 498.00
6876	40	Outboard Bearings	4	\$ 244.00	\$ 976.00
6876	50	Oil Seals	6	\$ 77.54	\$ 465.24
6876	60	Bearing Housing Gaskets	4	\$ 23.07	\$ 92.28
6876	70	Case Gasket	4	\$ 13.84	\$ 55.36
6876	80	Gland Bolt Hex Nuts	8	\$ 9.23	\$ 73.84
6876	90	Gland Bolt Studs	8	\$ 74.76	\$ 598.08
6876	100	Gland Bolts	8	\$ 24.92	\$ 199.36
6876	110	Gland Assembly	4	\$ 361.90	\$ 1,447.60
6876	120	Gland Guide Pins	4	\$ 34.15	\$ 136.60
6876	130	Gland Screws	8	\$ 9.23	\$ 73.84
6876	140	Set Screw Sleeve Nut	8	\$ 9.23	\$ 73.84
6876	150	Bearing Lock Nut	2	\$ 30.46	\$ 60.92
6876	160	Bearing Lock Washer	2	\$ 14.00	\$ 28.00
6876	170	Shaft Sleeve O-Rings	4	\$ 9.23	\$ 36.92
6876	180	Packing	24	\$ 46.00	\$ 1,104.00
6876	190	Shaft Sleeves	4	\$ 2,556.00	\$ 10,224.00
6876	200	RH Sleeve Nut	2	\$ 1,114.00	\$ 2,228.00
6876	210	LH Sleeve Nut	2	1,114.00	\$ 2,228.00

Comment
Supervisory labor to help Parsons ave employees remove existing rotating assembly from case and install the new oil seals & bearings utilizing Parsons equipment and shop facilities.
Supervisory labor to help Parsons Ave employees remove existing rotating assembly from case and install the new oil seals and bearings utilizing Parsons equipment and shop facilities.