

0098-2016 - SUMMARY of Modifications - Pierce Ladder Contract.docx

Summary

12/29/2015

Item	Description	Cost
1	Eliminate MSA TIC (-\$13730) camera but keep charger (\$1280)	-\$12,450
2	Eliminate extended front bumper and cord reel	-\$2,950
3	Eliminate camera system in tiller cab	-\$2,794
4	Eliminate 2 cord reels from tractor	-\$1,968
5	Change saw tray slides to low profile like generator P4/D4	-\$300
6	Eliminate tie off point on trailer	-\$204
7	Relocate hinge on outrigger from bottom to front side x2	\$150
8	Add Magneticmic to cab \$25-\$50 ea x3	\$150
9	Add doors to ends of rear under seat compartment	\$204
10	Add 2" + to pike pole storage	\$310
11	Relocate hinge side on turntable mansaver to curb side	\$349
12	Add DOT lighting to trailer	\$390
13	Add coat hooks to grab bars	\$400
14	Add spotlight to outrigger Rigid 20221	\$819
15	Relocate pedestal cover hinge to rear	\$850
16	Change generator to Stadco CD30 Pierce	\$1,050
17	Add backup and right turn camera with 1 monitor for driver	\$1,080
18	Change headlights to LED JW Speaker 8800	\$1,288
19	Relocate steps to tiller cab towards rear	\$3,308
20	Add Vogle lube to chassis	\$6,984
		-\$3,334