

Customer				Service Request	
Estimate #	896646			Service Request #	5818792
Customer	CITY OF COLUMBUS (OH)			Unit Information	
Account #	10429	Payment Terms	NET 30	Customer Vehicle #	
Contact	TONY FEATHERSTONE			Model	TA60
Email	tfeathers@columbus.gov			Chassis VIN #	3HAEUTAR4ML326185
Phone		Fax		Mileage	
Mobile				Unit Serial #	0321EL3279
Altec Representative				Assy Serial #(FA)	037-76658191
Contact	Brian Daniel Howell			In-Service Date	03-Dec-2021
Email	brian.howell@altec.com				
Phone		Fax			
This Estimate Expires: 25-NOV-23					
Notes:					

Item	Description	Hours	Labor	Material	Expenses	Total
1	~INITIAL INCIDENT EVALUATION	2.00	\$266.00	\$0.00	\$0.00	\$266.00
2	NOTE: CUSTOMER HAS THE RIGHT TO REFUSE, IN WRITING, THE PRELIMINARY DIELECTRIC TEST WITH THE UNDERSTANDING THAT IF THE UNIT DOES NOT PASS DIELECTRIC TEST AFTER REPAIRS ARE MADE, THEY ARE RESPONSIBLE FOR ANY ADDITIONAL COSTS OF FURTHER REPAIRS	0.00	\$0.00	\$0.00	\$0.00	\$0.00
3	~PERFORM 1 YEAR PM INSPECTION PER ANSI 92.2 2009 SECTION 8.2.5 PER ALTEC'S MAJOR UNIT DAMAGE GUIDELINES	--	\$675.00	\$139.31	\$0.00	\$814.31
4	~PERFORM STRUCTURAL LOAD TEST PER ALTEC'S MAJOR UNIT DAMAGE GUIDELINES (ADVISE IF ADDITIONAL REPAIRS ARE NEEDED)	1.50	\$199.50	\$0.00	\$0.00	\$199.50
5	~PERFORM DOT INSPECTION PER ALTEC'S MAJOR UNIT DAMAGE GUIDELINES (ADVISE IF ADDITIONAL REPAIRS ARE NEEDED)	--	\$190.00	\$1.28	\$0.00	\$191.28
6	TROUBLESHOOT POSSIBLE DAMAGE TO OUTRIGGERS	1.00	\$133.00	\$0.00	\$0.00	\$133.00
7	TRAVEL TIME TO/FROM SUBLET LOCATIONS	4.00	\$532.00	\$0.00	\$0.00	\$532.00
8	(SUBLET) TROUBLESHOOT & REPAIR CHASSIS DAMAGE (LABOR)	0.00	\$0.00	\$0.00	\$74,032.40	\$74,032.40
9	(SUBLET) TROUBLESHOOT & REPAIR CHASSIS DAMAGE (MATERIAL)	0.00	\$0.00	\$0.00	\$110,672.20	\$110,672.20
10	~REPLACE DAMAGED S/S SIDE PACK	10.00	\$1,330.00	\$10,166.00	\$0.00	\$11,496.00
11	SUPPLIES AND ENVIRONMENTAL DISPOSAL FEES	0.00	\$0.00	\$0.00	\$200.00	\$200.00
12	FREIGHT ESTIMATE	0.00	\$0.00	\$0.00	\$1,623.29	\$1,623.29
13	REMOVE THEN REINSTALL FRONT OUTRIGGER ASSEMBLY (REQUIRED IN ORDER TO REPLACE SIDE PACK)	18.00	\$2,394.00	\$0.00	\$0.00	\$2,394.00
	Totals	36.50	\$5,719.50	\$10,306.59	\$186,527.89	\$202,553.98

*This estimate is provided with the understanding that items may be discovered during the repair process that may require additional labor and/or materials to repair. Examples would include, but are not limited to, hidden damages or items that were not clearly visible or known

at the time of estimate, damaged internal components, fasteners and pins that may be rusted, seized or broken.

**This estimate does not include City, County, State or Federal taxes.

***Transportation or towing of the vehicle is not included in the estimate unless specified.

****Freight charges are estimated and may be adjusted to reflect the actual cost incurred on the invoice.

Please sign below to authorize this estimate			
Printed Name:	P.O.		Date:
Signature:			Would you like to keep salvageable parts removed from the unit?
			Yes No

Altec Service Group Limited Warranty

Products rebuilt or repaired by Altec Service Group are warranted to be free from defects in material and workmanship at the time of rebuild/repair subject to the following provisions:

- § Labor Coverage: For a period of six (6) months following the date of repair, no charge for labor shall be made for a repair or replacement by the Altec Service Group.
- § Travel Coverage: For a period of thirty (30) days following the date of repair, no charge for travel shall be made for a repair or replacement at the customers location by the Altec Service Group.
- § Parts Coverage: For a period of one (1) year following the date of repair, Altec will at its option, repair or replace any part found to be defective in material or workmanship at the time of repair.
- § This warranty is limited to parts that are repaired or replaced by the Altec Service Group. Authorization and coverage of this warranty will be at the discretion of the Altec Service Group.
- § Accessory items are excluded from this warranty and will be warranted from the original manufacturer.

This limited warranty is expressly in lieu of any other warranties, express or implied, including, but not limited to, any warranty of merchantability or fitness for a particular purpose. Except as specified above, no associate, agent or representative of Altec is authorized to extend any warranty on Altec's behalf. Remedies under this limited warranty are expressly limited to the provision and installation of parts and labor, as specified above, and any claims for other loss or damages of any type (including, but not limited to, loss from failure of the product to operate for any period of time, other economic or moral loss, or direct, immediate, special, indirect, incidental or consequential damage) are expressly excluded.

Ser War 2-10 Altec Industries, Inc.

Rpl W/S

Rpl Lt Frt Tire

Rpl Engine Long Block #DR776BRX:CX

Engine Core

Rpl Hood Seal Recirc Assy #38797C4:IH
Rpl Lt Wiper Arm Assy #3535049C2:IH
Rpl Rt Wiper Arm Assy #3535050C3:IH
Rpl Both Wiper Blades #91005222:R61
Rpl Both Cummins Graphic #4096176C1:IH
Rpl Both Hood Graphic Cummins #4098274C1:IH
Rpl Radiator Outlet Pipe Engine #4075689C2:IH
Rpl Radiator Hose Outlet Engine #4075688C2:IH
Rpl Radiator Outlet Hose #3879521C1:IH
Rpl Radiator Inlet Hose Engine #4075686C2:IH
Rpl Radiator Module Assy #2522406C91:IH
Rpl Radiator, Surge Tank Assy #2516757C2:IH
Rpl Heater Hoses 6 #L2643493:IH
Rpl Module Charge Air Cooler #2522407C91:IH
Rpl Pipe, Mid-High O/C Hard Line Fe #2601798C91:IH
Rpl Fan Clutch DMA2S SE 24 #HOR99A82432:I61
Rpl Hood Assy #4088267C91:IH
RplFrt Bumper Assy #3610930C3:IH
Rpl Bar, Hood Assist Torsion, Mid #3558736C2:IH
Rpl Bar Hood Pivot Assist Torsion RT #3558737C2:IH
Engine Insulator Rear Mt 2 #3549169C2:IH
* Fabricated Parts :
* SMC Adhesives, Fiberglass Material & Misc. Supplies

Rpl Lt Frt Fender Ext #3566716C4:IH
Rpl Power Steering Reservoir #4043002C92:IH
Rpl Frt Grille Assy #FLTG3551015:IH
Rpl Rt H/L Assy #FLTHL3765680:IH
Rpl Lt H/L Assy #FLTHL3765679:IH
Rpl Lt Frt Fender Mirror Assy #3554617C3:IH
Rpl Rt Frt Fender Mirror Assy #3554618C3:IH
Rpl Lt Side Rear View Mirror Assy #4049612C94
Rpl Lt Outside Door Handle #4053943C93:IH
Rpl Both Hood Straps #3544924C1:IH
Rpl Radiator Support Rod #3605649C2:IH
Rpl Radiator Support Rod Stay #3564534C2:IH
Rpl Wiper Motor Baffle Cover Cowl #3710650C3:IH
Rpl Lt Cab Door Shell #4172798W91E:IH
Rpl Reman Gear Box Steering #ZRXHD94PQ:ISH
Reman Gear Box Core #ZRXHD94PQ:ISH
Rpl W/S Washer Tank Assy W/O Sensor #3728178C92:IH
Rpl Hose, Flexible Air, 4" #3558834C2:IH
Rpl Hose, Flexible Air, Cac 3.5 DI #3558834C2:IH
* Fabricated Parts :
* SMC Adhesives, Fiberglass Material & Misc. Supplies

Rpl Radiator Module, Rt Hand Side #2522413C91
Rpl Radiator Module, Left Hand Side #2522412C91:IH
Rpl Frame Kit Radiator Top #2601780C91:IH
Rpl A/C Condense#2519439C1:IH
Rpl Lt Panel Splash Assy #3830912C93:IH
Rpl Lt Frt Rim White Steel #29039PKWHT21:AWE
Rpl 2 Spring Hood Cable Drive Plus #3598407C1:IH
Rpl All Frt Bumper Bolts 4 #3579048C1:IH
Rpl All 4 Spring Hood Cables #590279C2
Rpl Housing Flywheel #5339507:CE
Rpl Oil Seal #5405392:CE
Rpl Oil Pan Gasket #3930408:CE
Rpl Flexplate #3937020:CE
Rpl Frt Engine Insulators #1664723C5:IH
Rpl 2 M16 X 10MM Bolts #31077R1:IH
Rpl 2 Bolt Hex Flg HD Metric M16X9 #40203R1:IH
Rpl Fuel Filter #5303742:CE
Rpl Auto All-300RDS #3000RDSWEL:WEL

2 55-158 Intt-Nav F Spr LVS:7/SE

4 HT7832 Threaded Rod 7/8X32 Grade 8

8 DN5 Deep Nut (7/8-14)

8 UBW80 "U-Bolt Washers (7/8""") Hardened

1 Power Steering Filter

Pitman Arm

Draglink

Misc Frame / Huck Bolts

Part #	Qty	Description
035610028	1	FILLER BREATHER; HYDRAULIC; EXTERNAL TANK MOUNT; 10 MICRON; NITRILE (BUNA-N/NBR) SEALS; 7.50 INCH DIPSTICK
970100835	1	PLACARD;ENGLISH;INFORMATION;;;SE RVICE TESTING;PUNCH HOLE STYLE;SOLD INDIVIDUALLY;.....
970144852	1	PLACARD; US DOT ANNUAL INSPECTION
970288189	1	FILTER ELEMENT; HYDRAULIC; RETURN; ELEMENT ONLY; 10 MICRON ABSOLUTE; INORGANIC MICROFIBER; 30 GPM; 145 PSI; NITRILE (BUNA- N/NBR) SEALS
991214937	1	STREETSIDE SIDEPACK;;CITY OF COLUMBUS;150.00 IN L;46.00 IN H;18.00 IN W;;