

Sutphen Corporation  
 6450 Eiterman Rd  
 Dublin, Ohio 43016  
 tschafer@heritagefireequipment.  
 com



**ADDRESS**

John King  
 City of Columbus  
 3675 Parsons Avenue  
 Ohio  
 Columbus, OH 43207

**SHIP TO**

John King  
 City of Columbus  
 3675 Parsons Avenue  
 Columbus, Ohio 43207

Estimate 2019-427

DATE 10/31/2019

**HS NUMBER**

6354

ITEM/DESCRIPTION	QTY	RATE	AMOUNT
<b>10114608</b> Bucket, Sutphen, SPH100	1	32,284.05	32,284.05
<b>10087877</b> Bucket Mount, Sutphen, SPH100, Left Side	1	1,300.72	1,300.72
<b>10087878</b> Bucket Mount, Sutphen, SPH100, Right Side	1	1,300.72	1,300.72
<b>10109992</b> Yoke, Sutphen, SPH	1	6,650.36	6,650.36
<b>Paint</b> Yoke Columbus Red	1	850.00	850.00
<b>Service Labor</b> Removal of Bucket and Yoke From Ladder -disassemble bucket from yoke -disassemble yoke from ladder -disassemble water way from yoke -disassemble wiring and hydraulic bucket from yoke	10	116.45	1,164.50
<b>Service Labor</b> Disassemble Bucket Components -disassemble useable bucket components -save and inventory all undamaged components	25	116.45	2,911.25

444200  
 PA 442627

VEHICAL MAINT'S REPAIR  
 SERVICES

ITEM/DESCRIPTION	QTY	RATE	AMOUNT
<b>Service Labor</b> Assemble Bucket Components in New Bucket -reinstall all undamaged components of the bucket -stokes arms - parapet ladder -function test -D-Rings -handrails -lighting -bucket weldment left and right -left and right monitor and waterway - hydraulics	75	116.45	8,733.75
<b>Service Labor</b> Install New Yoke and Bucket on Aerial Boom	10	116.45	1,164.50
<b>Tags</b> Misc. Pump Panel Tags	1	130.00	130.00
<b>Shop Supplies-Misc</b> nut and bolts hucks	1	189.62	189.62
<b>MISC.</b> Door Skins -door skins and graphics shall be reused	1	0.00	0.00
<b>Ladder Test</b> A 3rd part ladder test shall be provide. Documentation shall be provided of the test.	1	875.00	875.00
<b>Service Estimate Disclaimer</b> The prices listed on this estimate are good for 30 days. This is an estimate of the parts and labor necessary to complete the repair. As so, the final price may vary. The final price may vary up to 10% above the estimate without additional customer approval to proceed. The apparatus owner is responsible for transportation and insurance on the vehicle to and from Heritage Fire Equipment.	1	0.00	0.00
<b>Inspection</b> Once bucket is removed from yoke and truck it will be inspected to evaluate the option to repair the damage in lieu of replacing bucket	1	116.45	116.45

BT 28299

Quote is valid for 30 days and does not include shipping.

TOTAL	\$57,670.92
-------	-------------

Accepted By

Accepted Date