LPA RX 851 WD

Page 1 of 2 Rev. 06/09

Ver. Date 02/27/2022 PID ######

35-WD PARCEL E. SECOND AVENUE ALL RIGHT, TITLE AND INTEREST IN FEE SIMPLE IN THE FOLLOWING DESCRIBED PROPERTY WITHOUT LIMITATION OF EXISTING ACCESS RIGHTS IN THE NAME AND FOR THE USE OF THE CITY OF COLUMBUS, FRANKLIN COUNTY, OHIO

Grantor/Owner, for himself and his heirs, executors, administrators, successors and assigns, reserves all existing rights of ingress and egress to and from any residual area (as used herein, the expression "Grantor/Owner" includes the plural, and words in the masculine include the feminine or neuter).

[Surveyor's description of the premises follows]

Situate in the State of Ohio, County of Franklin, City of Columbus, located in Fractional Section 4, Township 5, Range 22, Refugee Lands, being part of Lot 99 of Terrace View Addition of record in Plat Book 4, Page 250, as conveyed to FK II Limited Partnership by deed of record in Instrument Number 200811140166186, records of the Recorder's Office, Franklin County, Ohio, and being more particularly described as follows;

Being a parcel of land lying on the left side of the Centerline of Right-of-Wav as delineated upon the E. Second Avenue Right-of-Way Plan on file with the City of Columbus (3407-E);

Beginning at a point in the existing northerly right of way line of E. Second Avenue and at the common corner of Lots 100 and 99 of said Terrace View Addition; said point being 25.00 feet left of Centerline Right-of-Way station 28+44.99;

Thence North 03 deg. 44 min. 12 sec. East, a distance of 5.00 feet along said common line of Lots 100 and 99 to an iron pin set, being 30.00 feet left of Centerline Right-of-Way station 28+45.01;

Thence the following three (3) courses and distances across said Lot 99;

1. Thence South 86 deg. 33 min. 10 sec. East, a distance of 20.00 feet to an iron pin set, being 30.00 feet left of Centerline Right-of-Way station 28+65.01;

Rev. 06/09

- 2. Thence South 03 deg. 44 min. 12 sec. West, a distance of 3.00 feet to an iron pin set, being 27.00 feet left of Centerline Right-of-Way station 28+65.00;
- 3. Thence South 86 deg. 33 min. 10 sec. East, a distance of 10.00 feet to an iron pin set in the common line of Lots 99 and 98 of said Terrace View Addition, being 27.00 feet left of Centerline Right-of-Way station 28+75.00;

Thence South 03 deg. 44 min. 12 sec. West, a distance of 2.00 feet along the common line of said Lots 99 and 98 to a point in the existing northerly right of way line of E. Second Avenue, at the common corner of said Lots 99 and 98; said point being 25.00 feet left of Centerline Right-of-Way station 28+74.99;

Thence North 86 deg. 33 min. 10 sec. West, a distance of 30.00 feet along the existing northerly right of way line of E. Second Avenue and the southerly line of said Lot 99, to the **Point of Beginning** of the herein described parcel, containing 120 square feet (0.003 acres), more or less, of which 0.000 acres lies within the existing Present Road Occupied.

Of the above described area, 120 square feet are contained within Franklin County Auditor's Parcel 010-054731.

Bearings are based on the Ohio State Plane Coordinate System, South Zone, NAD 83 (NSRS 2007), as established from a GPS survey in October 2017, and are based on the bearing of South 86 deg. 41 min. 21 sec. East for the centerline of E. Second Avenue, as determined by occupying Franklin County Geodetic Control Monuments "COC17-82" and "TACKETT".

All iron pins set are 5/8 inches in diameter rebar by 30 inches long with a yellow plastic cap stamped STANTEC.

This description was prepared by Steven E. Rader, registered surveyor 7191, and is based upon a field survey for the City of Columbus in 2017, by Stantec Consulting Services, Inc., under the direction of said surveyor.

Instrument reference as of the date this survey was prepared: Instrument Number 200811140166186, of the Recorder's Office, Franklin County, Ohio.

STANTEC CONSULTING SERVICES INC.