## ORD #0782-2018, Division of Water Joyce Tank 2018 Exterior Painting Imp's C.I.P. No. 690477-100012, Contract No. 2223 Bid Tabulation, Opened 2/28/18 Engineer's Estimate = \$1,500,000

UCL, Inc. A1 Industrial Painting, Inc. American Suncraft Co., Inc. Ref. Item # # Description Qty Units Materials Labor Extension Materials Labor Extension **Materials** Labor Extension Joyce Tank Remove Existing Exterior Coating LS SPEC and Recoat, See Schedule A 1 \$240,000.00 \$445,000.00 \$685,000.00 \$433,247.00 \$347,093.00 \$780,340.00 \$492,440.00 \$454,560.00 \$947,000.00 Joyce Tank Repair Existing Interior Dry, All SPEC Surfaces, See T.S. 4.1.F and Schedule B \$23,000.00 LS \$46,000.00 2 1 \$1,500.00 \$3,500.00 \$5,000.00 \$23,000.00 \$14,300.00 \$14,300.00 \$28,600.00 Joyce Tank Exterior and Interior Base Plate SPEC Repair, See T.S. 4.1.A and Schedule C LS \$2,500.00 \$6,500.00 \$9,000.00 \$3,000.00 \$7,800.00 \$10,800.00 \$7,500.00 \$3,700.00 3 1 \$11,200.00 Joyce Tank Interior Wet Spot Repair, See T.S. SPEC 4.1.E LS \$17,000.00 \$40,000.00 \$100,000.00 \$160,550.00 4 1 \$57,000.00 \$60,550.00 \$35,000.00 \$50,200.00 \$85,200.00 Install Caulking, Sikaflex 1a, As Directed, 10.3 SPEC fl. Oz. Tubes, Per Schedule H, Contingency Item 100 \$12.00 \$8.50 \$9.00 5 EA \$45.00 \$5,700.00 \$125.00 \$13,350.00 \$120.00 \$12,900.00 Joyce Tank Replace North and South Murals, SPEC See T.S. 4.2.A and Schedule F LS \$5.000.00 \$20,000.00 \$25,000.00 \$34,550.00 \$28,000.00 \$62,550.00 \$31.800.00 \$37.800.00 \$69.600.00 6 Joyce Tank Repair Hole in Gound Entryway, SPEC See T.S. 4.1.B LS \$300.00 \$950.00 \$500.00 \$700.00 \$600.00 7 \$650.00 \$1,200.00 \$600.00 \$1,200.00 1 Joyce Tank Install New Hatch and Frost-Free LS 8 SPEC Vents on Roof, See T.S. 4.2.C \$11,000.00 \$7.000.00 \$18,000.00 \$550.00 \$1,700.00 \$2,250.00 \$12,900.00 1 \$3,500.00 \$16,400.00 Joyce Tank Kick Plate Modification, See T.S. SPEC 4.1.B 9 LS \$1,500.00 \$4,000.00 \$5,500.00 \$1,100.00 \$1,050.00 \$2,150.00 \$1,800.00 \$2,400.00 \$4,200.00 Climbing and Inspection Gear, Furnished and SPEC Delivered, Per T.S. 4.3 LS \$6,800.00 \$200.00 \$7,000.00 \$8,000.00 \$0.00 \$8,000.00 \$8,000.00 \$1,200.00 \$9,200.00 10 1 SPEC Seal Coat for Driveway, T.S. 3.14.F LS \$15,000.00 \$5,000.00 \$20,000.00 \$3,000.00 \$1,200.00 \$4,200.00 \$2,000.00 \$500.00 \$2,500.00 Mobilization/Demobilization Fee (Not To SPEC Exceed 5% of sum of Items 1 Through 11) \$7,000.00 \$7,500.00 \$15,000.00 \$41,550.00 \$56,550.00 \$14,000.00 \$14,000.00 LS \$14,500.00 \$28,000.00 12 1 SUBTOTAL: \$852,650.00 \$1,147,940.00 \$1,216,000.00 13 SPEC CONTINGENCY (15%) \$127.897.50 \$172,191.00 \$182.400.00 **GRAND TOTAL:** \$980,547.50 \$1,320,131.00 \$1,398,400.00 % DIFFERENCE FROM ENGINEER'S ESTIMATE -34.63% -11.99% -6.77% % DIFFERENCE WITHIN LOWEST BIDDER N/A 34.6% 42.6% Contract Compliance No 31-1697362 (exp. 2/21/19, MAJ, 5810) 26-3962924 (exp. 7/19/19, MAJ, 22427) 31-1286248 (EXPIRED, MAJ, 4976)

\*Corrected contingency & grand total.

UCL, Inc. 2025 Stapleton Ct., Cincinnati, OH 45240 Pete Kontopos, President (513) 674-1666 <u>unitedpainting@fuse.net</u> A1 Industrial Painting, inc. 894 Coitsville Hubbard Rd. Youngstown, OH 44505 Jack Maillis (330) 750-9441 jackmaillis@aiindustrialpainting.com

American Suncraft Co., Inc. 10836 Schiller Rd. Medway, OH 45341 Lisa Boling, V.P. (937) 849-9475 lisa@asuncraft.com

|      |      |             |     |       |           | UCL, Inc. |           | A1 Ind    | ustrial Painti | ng, Inc.  | Ameri     | can Suncraft C | o., Inc.  |
|------|------|-------------|-----|-------|-----------|-----------|-----------|-----------|----------------|-----------|-----------|----------------|-----------|
| Ref. | Item |             |     |       |           |           |           |           |                |           |           |                |           |
| #    | #    | Description | Qty | Units | Materials | Labor     | Extension | Materials | Labor          | Extension | Materials | Labor          | Extension |
|      |      |             |     |       |           |           | -         |           |                |           | • 1       | -              |           |

Katerina Kontopos, Secy, Treas.

Ron Boling, President

## ORD #0782-2018, Division of Water

Joyce Tank 2018 Exterior Painting Imp's

C.I.P. No. 690477-100012, Contract No. 2223

## Bid Tabulation, Opened 2/28/18

| Engi | ineer's | Estimate = \$1,500,000                           |               |         | NO                          | ON-RESPONSI       | VE   |
|------|---------|--|---------------|---------|-----------------------------|-------------------|--|
|      |         |  |               |         | Horizon Bros. Painting Corp |                   |  |
|      | Item    | -  |               |         |                             |                   | _  |
| #    | #       | Description                                      | Qty           | Units   | Materials                   | Labor             | Extension  |
|      | ~~~~~   | Joyce Tank Remove Existing Exterior Coating      |               |         |                             |                   | <b>.</b>   |
| 1    | SPEC    | and Recoat, See Schedule A                       | 1             | LS      | \$147,160.00                | \$220,740.00      | \$367,900.00                                     |
|      | app a   | Joyce Tank Repair Existing Interior Dry, All     |               |         | <b>#0.000.00</b>            | ¢140 <b>2</b> 000 | <b>#247</b> 00.00                                |
| 2    | SPEC    | Surfaces, See T.S. 4.1.F and Schedule B          | 1             | LS      | \$9,880.00                  | \$14,820.00       | \$24,700.00                                      |
| _    |         | Joyce Tank Exterior and Interior Base Plate      |               |         | <b>.</b>                    |                   | to =00.00  |
| 3    | SPEC    | Repair, See T.S. 4.1.A and Schedule C            | 1             | LS      | \$3,880.00                  | \$5,820.00        | \$9,700.00                                       |
|      |         | Joyce Tank Interior Wet Spot Repair, See T.S.    |               |         |                             |                   |  |
| 4    | SPEC    | 4.1.E  | 1             | LS      | \$19,160.00                 | \$28,740.00       | \$47,900.00                                      |
|      |         |  |               |         |                             |                   |  |
|      |         | Install Caulking, Sikaflex 1a, As Directed, 10.3 | 100           |         | <b>t z o o</b>              |                   | <b>.</b>   |
| 5    | SPEC    | fl. Oz. Tubes, Per Schedule H, Contingency Item  | 100           | EA      | \$5.00                      | \$15.00           | \$2,000.00                                       |
|      |         | Joyce Tank Replace North and South Murals,       |               |         | ***                         | * • • • • • • • • |  |
| 6    | SPEC    | See T.S. 4.2.A and Schedule F                    | 1             | LS      | \$29,160.00                 | \$43,740.00       | \$72,900.00                                      |
| _    |         | Joyce Tank Repair Hole in Gound Entryway,        |               |         | ****                        |                   | <b>.</b>   |
| 7    | SPEC    | See T.S. 4.1.B                                   | 1             | LS      | \$200.00                    | \$300.00          | \$500.00   |
| _    |         | Joyce Tank Install New Hatch and Frost-Free      |               |         |                             |                   |  |
| 8    | SPEC    | Vents on Roof, See T.S. 4.2.C                    | 1             | LS      | \$4,800.00                  | \$7,200.00        | \$12,000.00                                      |
|      | ~~~~~   | Joyce Tank Kick Plate Modification, See T.S.     |               |         | <b>**</b>                   | <b>**</b>         | <b>* *</b> • • • • • • • • • • • • • • • • • • • |
| 9    | SPEC    |  | 1             | LS      | \$2,000.00                  | \$3,000.00        | \$5,000.00                                       |
|      | ~~~~~   | Climbing and Inspection Gear, Furnished and      |               |         | <b>**</b>                   | <b>*</b> 4 000 00 | <b>\$</b> \$\$\$\$\$\$\$\$\$                     |
| 10   |         | Delivered, Per T.S. 4.3                          | 1             | LS      | \$3,200.00                  | \$4,800.00        | \$8,000.00                                       |
| 11   | SPEC    | Seal Coat for Driveway, T.S. 3.14.F              | 1             | LS      | \$2,000.00                  | \$3,000.00        | \$5,000.00                                       |
| 10   |         | Mobilization/Demobilization Fee (Not To          | 1             | ТG      | ¢c cc1 00                   | \$0.00C.00        | ¢16,660,00                                       |
| 12   | SPEC    | Exceed 5% of sum of Items 1 Through 11)          | 1             | LS      | \$6,664.00                  | \$9,996.00        | \$16,660.00                                      |
|      |         | SUBTOTAL:  |               |         |                             |                   | \$572,260.0                                      |
| 13   | SPEC    | CONTINGENCY (15%)                                |               |         |                             |                   | \$85,839.0                                       |
|      |         | GRAND TOTAL:                                     |               |         |                             |                   | \$658,099.0                                      |
|      |         | % DIFFERENCE FROM ENGINEER                       | 'S EST        | IMATE   |                             |                   | -56.139  |
|      |         | % DIFFERENCE WITHIN LOW                          | <u>'EST B</u> | IDDER   |                             |                   | -32.99   |
|      |         | Contract C                                       | omplia        | nce No. | 38-33                       | 94434 (EXPIRE     | ED, MAJ, 7654                                    |
|      |         |  |               |         | *Corrected cont             | ingency & grand   | d total.   |
|      |         |  |               |         |                             |                   |  |

NON-RESPONSIVE; BIDDER NOT PRE-QUALIFIED TO BID.

Horizon Bros. Painting Corp. 1053 Kendra Lane Howell, MI 48843 Ded Gjolaj, President (810) 632-3362 x1 office@horizonbros.com

|      |      |             |     |       | Horizo         | n Bros. Paintin | g Corp    |
|------|------|-------------|-----|-------|----------------|-----------------|-----------|
| Ref. | Item |             |     |       |                |                 |           |
| #    | #    | Description | Qty | Units | Materials      | Labor           | Extension |
|      |      |             |     |       | Andy (810) 632 | 3367            |           |

Andy (810) 632-3362

| General Info |   |
|--------------|---|
| Number:      | 690477-100012   |
| Description: | Joyce Tank 2018 Exterior Painting Improvements, Contract 2223 |
| Deadline:    | 2018-02-28 20:00:00 UTC                                       |

| Bids                       |                |               |                         |
|----------------------------|----------------|---------------|-------------------------|
| Business                   | Bid Total      | Signed by     | Opened at               |
| ucl inc                    | \$980,547.50   | pete kontopos | 2018-02-28 20:01:54 UTC |
| a1 industrial painting inc | \$1,320,131.00 |               |                         |
| American Suncraft Co.,     |                |               |                         |
| Inc.                       | \$1,398,400.00 | Lisa Boling   | 2018-02-28 20:01:03 UTC |
| Horizon Bros Painting      |                |               |                         |
| Corp                       | \$658,099.00   | Ded Gjolaj    | 2018-02-28 20:01:21 UTC |

| 2018-02-28 19:38:18 UT |   |
|------------------------|---|
|                        | С |
| 2018-02-28 17:43:52 UT | С |
|                        |   |
| 2018-02-28 14:43:54 UT | С |

2018-02-28 17:39:46 UTC NON-RESPONSIVE