

ORD 2158-2024  
 RFQ028122  
 Opened 7/18/24

Vendor account	Type	Line n	Status	Product name	Quantity	Unit	Comment	Unit price in transaction currency	Total net amount in transaction currency
				RFQ028122					
010267 - Agilent	Header	0	Created		0.00				142,566.35
010267	Line	10	Received	5977C Inert Plus MSD Turbo EI Bundle G7077CA	1.00	EA	5977C inert Plus MSD Turbo EI Bundle G7077CA Agilent Intuvo 900 G	123,629.83000	123,629.83
010267	Line	20	Received	Method and Application Consulting On site H2149A	1.00	EA	H2149A	9,633.28000	9,633.28
010267	Line	30	Received	Intuvo Exhaust Kit G4580-68300	1.00	EA	G4580-68300	152.40000	152.40
010267	Line	40	Received	Intuvo Polymide Gasket 5/pack 5190-9072	1.00	EA	5190-9072	78.60000	78.60
010267	Line	50	Received	Intuvo S/SL Jumper Chip G4587-60575	1.00	EA	G4587-60575	113.40000	113.40
010267	Line	60	Received	Liner, Ultra Inert straight 1 mm ID 5190-4047	1.00	EA	5190-4047	25.86000	25.86
010267	Line	70	Received	Extraction Lens 9 mm G3870-20449	1.00	EA	G3870-20449	120.60000	120.60
010267	Line	80	Received	Site Prep Package for 5975C G3391A	1.00	EA	G3391A	34.13000	34.13
010267	Line	90	Received	DB-624 UI 20m 0.18mm 1.00um intuvo 121-1324UI-INT	1.00	EA	121-1324UI-INT	481.20000	481.20
010267	Line	100	Received	GCMS Application for EPA method 624 G7022B	1.00	EA	G7022B	2,771.32000	2,771.32
010267	Line	110	Received	Latest NIST MS Library Bundle G1033C	1.00	EA	G1033C	4,595.40000	4,595.40
010267	Line	120	Received	Intuvo Install Kit 19199U	1.00	EA	19199U	575.73000	575.73
010267	Line	130	Received	Tipseal Maintenance Kit G7077-67018	1.00	EA	G7077-67018	354.60000	354.60