## **EXHIBIT A**

Page 1 of 3

LPA RX 887 T Rev. 07/09

Ver. Date 10/01/2012 PID 88430

## PARCEL 3-T HAGUE AVENUE-VALLEYVIEW DRIVE TEMPORARY EASEMENT FOR THE PURPOSE OF PERFORMING THE WORK NECESSARY TO DRIVEWAY CONSTRUCTION & COMPLETE GRADING FOR 12 MONTHS FROM DATE OF ENTRY BY THE CITY OF COLUMBUS, FRANKLIN COUNTY, OHIO

[Surveyor's description of the premises follows]

Situated in the State of Ohio, County of Franklin, City of Columbus, being located in Virginia Military Survey Number 1390, and being a part of that 10.388 acre tract described in a deed to **The Young Men's Christian Association of Columbus, Ohio**, of record in Deed Book 1919, page 118, all records referenced herein are on file at the Office of the Recorder for Franklin County, Ohio, being a parcel of land located on the right side of the centerline of survey and right-of-way for Valleyview Drive, as said centerline is depicted on the centerline plat for the Hague Avenue-Valleyview Drive right-of-way plans, of record in Instrument Number 201209270144475 (Plat Book 115, pages 36-37), and being further bounded and described as follows:

Commencing for reference from the northwest corner of said 10.388 acre tract, being the northeast corner of that 3.000 acre tract described in a deed to Luther B. Turner Lodge No. 732 Free & Accepted Masons, of record in Instrument Number 201011160153898, said corner being on the existing centerline of survey and right-of-way for Valleyview Drive, and said corner being at Valleyview Drive centerline of survey and right-of-way Station 35+53.31;

Thence **South 03 degrees 38 minutes 49 seconds East**, along the west line of said 10.388 acre tract, along the east line of said 3.000 acre tract, a distance of **30.16 feet** to a point on the existing south right-of-way line for said Valleyview Drive, said point being 30.00 feet right of Valleyview Drive centerline of survey and right-of-way Station 35+56.39, and said point being the **TRUE POINT OF BEGINNING** for the herein described temporary easement;

Thence across said 10.388 acre tract along the following five (5) described courses:

1. **South 87 degrees 46 minutes 53 seconds East**, along the existing south right-of-way line for said Valleyview Drive, a distance of **15.99 feet** to a point, said point being 30.00 feet right of Valleyview Drive centerline of survey and right-of-way Station 35+72.38;

**LPA RX 887 T** 

2. South 02 degrees 13 minutes 07 seconds West, along a line perpendicular from the previous course, a distance of 6.00 feet to a point, said point being 36.00 feet right of Valleyview Drive centerline of survey and right-of-way Station 35+72.38;

- 3. South 87 degrees 46 minutes 53 seconds East, along a line parallel to and 6.00 feet southerly from the existing south right-of-way line for said Valleyview Drive, a distance of 10.00 feet to a point, said point being 36.00 feet right of Valleyview Drive centerline of survey and right-of-way Station 35+82.38;
- 4. North 02 degrees 13 minutes 07 seconds East, along a line perpendicular from the previous course, a distance of 6.00 feet to a point on the existing south right-of-way line for said Valleyview Drive, said point being 30.00 feet right of Valleyview Drive centerline of survey and right-of-way Station 35+82.38;
- 5. South 87 degrees 46 minutes 53 seconds East, along the exiting south right-of-way line for said Valleyview Drive, a distance of 345.58 feet to a point on the east line of said 10.388 acre tract, being on the west line of that original 9.555 acre tract described in a deed to The Glenwood Methodist Church of Columbus, Ohio, of record in Deed Book 1919, page 137 (N.K.A. Glenwood United Methodist Church, by a name change affidavit of record in Instrument Number 201109300124367), said point being 30.00 feet right of Valleyview Drive centerline of survey and right-of-way Station 39+27.96;

Thence South 03 degrees 38 minutes 49 seconds East, along the east line of said 10.388 acre tract, along the west line of said original 9.555 acre tract, a distance of 18.09 feet to a point, said point being 48.00 feet right of Valleyview Drive centerline of survey and right-of-way Station 39+29.81;

Thence across said 10.388 acre tract along the following four (4) described courses:

- 1. North 84 degrees 05 minutes 44 seconds West, a distance of 202.23 feet to a point, said point being 35.00 feet right of Valleyview Drive centerline of survey and right-of-way Station 37+28.00;
- 2. South 81 degrees 58 minutes 28 seconds West, a distance of 84.34 feet to a point, said point being 50.00 feet right of Valleyview Drive centerline of survey and right-of-way Station 36+45.00:

LPA RX 887 T

3. North 87 degrees 46 minutes 53 seconds West, along a line parallel to and 20.00 feet southerly from the existing south right-of-way line for said Valleyview Drive, a distance of **25.00 feet** to a point, said point being 50.00 feet right of Valleyview Drive centerline of survey and right-of-way Station 36+20.00;

4. North 76 degrees 57 minutes 42 seconds West, a distance of 63.93 feet to a point on the west line of said 10.388 acre tract, being on the east line of said 3.000 acre tract, said point being 38.00 feet right of Valleyview Drive centerline of survey and right-of-way Station 35+57.21;

Thence North 03 degrees 38 minutes 49 seconds West, along the west line of said 10.388 acre tract, along the east line of said 3.000 acre tract, a distance of 8.04 feet to the TRUE POINT OF **BEGINNING** for the herein described temporary easement.

The above described temporary easement contains an area of **0.107 acres** (including 0.000 acres within the present road occupied) within Franklin County Auditor tax parcel number 010-111270.

The bearings described herein are based on the centerline of survey and right-of-way for Valleyview Drive (South 87 degrees 46 minutes 53 seconds East) and grid north referenced to the North American Datum of 1983 (NSRS 2007 Adjustment) and the Ohio State Plane Coordinate System (South Zone), as established utilizing a GPS survey originating on Franklin County Engineer Survey Control Monuments "ST01" and "FCGS 5335".

The above description of a temporary easement was prepare and reviewed by Brian P. Bingham, Registered Professional Surveyor No. 8438 on June 19, 2012, is based on an actual survey performed in the field by American Structurepoint, Inc., and is true and correct to the best of my knowledge and belief.

American Structurepoint, Inc.	
Drive D. Die chore	Dete
Brian P. Bingham	Date
Registered Professional Surveyor No. 8438	