

1626 Cole Blvd, Suite 250 Golden, CO 80401 Voice: 303-301-7300 Fax: 303-384-9014

Customer	: Columbus Fire Department	Quote ID	COLU-2404-4STNS-MULTIZONE
Contact:	Brian Poling	Document Date	4/17/2024
Email:	BLPoling@Columbus.gov	Quote Expires:	7/10/2024
Phone:	614-724-7050		

1.0 Notes and Assumptions

Quoted:

Locution PrimeAlert IP add-on system (ties into existing Columbus, OH head-end system - the head-end system must be in place for this system to be fully functional). Quoted for:

4 Stations:

Station #10 - Multi-Zone Station #14 - Multi-Zone Station #17 - Multi-Zone Station #18 - Multi-Zone

Notes: Station #17 - RXUs are not needed to operate the TMUI-FM8 – these will be tied into the station's internet switch.

SSL-STA not quoted due to these being existing stations and this software was quoted during the original project.

Customer must ensure that good network connectivity exists between the central server and all station PCs, in order for the system to be fully functional.

It is the Customer's responsibility to ensure 120V power exists within 6' of all Locution provided station enclosure(s), amplifier(s), monitors/zone tracker(s), and reader board(s).

Includes full inst	allation. Installation to be provid	led by E	SI	
Part Num	Description	Qty	Unit Cost	Total
2.0 Station Software a 2.1 Software (Standard				
SSL-VSB-ST	PrimeAlert Remote Client add-on module for relay switching and advanced zoned audio/lighting (up to 10 devices)	15	1,986	29,790
SSL-VSC-01	PrimeAlert Remote Client add-on module for 1 Zone Tracker (for zoned systems)	4	1,029	4,116
2.2 Software (Custom/ none defined	nterfaces)			
2.3 Hardware - Basic LCPN33-MZ	Control Panel, Multi-zone: includes system power, multiple relays with relay backplane, isolated inputs, wire management, 120V surge- protection and isolation, with locked front panel door access. 2 chassis	4	9,075	36,300

TRLY-AU LOPT-EN-RX3-	Audio Controlled Relay Option: Add Relay Exter	nsion Unit, No Bus	4 3	208 850	832 2,550
NB RHT-PWS-CO	Master, 6 Relay S-18 Power Supply		4	174	696
MPCA	Station PC Assembly		4	1,540	6,160
RHL-RIA30	Radio Interface Unit - A		4	949	3,796
TUPS-15	Uninterrupted Power Su		4	418	1,672
TWIR-AV	Wire required per audio, requirements (if applical		1	24,263	24,263
LSWI-DB	Door Bell		16	116	1,856
	(Subtotal \$78,125)			·
2.4 Hardware - Audio					
MAMP-A24	Amplifier - Single 240W		4	1,869	7,476
MAMP-A12	Amplifier - Single 120W		2	1,539	3,078
TSPK-CL	Speaker - Ceiling		172	99	17,028
TSPK-CL-BM	Speaker - Ceiling - Blind	d Mount	49	149	7,301
TSPK-WB	Speaker - Wall Baffle		130	189	24,570
TSPK-HR	Speaker - Horn Volume Control		20	249	4,980
TAVC MAVC-25W-RM		Jount 25W 6 Position	36	79	2,844
MAVC-25W-RM	(Subtotal \$72,557)	8	660	5,280
		,			
2.5 Hardware - Visual			4	0.005	0.400
MZTS LNVR	Station Zone Tracker (T Night Vision Recessed I		4 57	2,295 229	9,180 13,053
LNVR LNVR-DL	Night Vision Recessed I		57 72	359	25,848
	DALI (Ramped)*		12	555	25,040
MLRB-1L-ET	Reader Board 1 Line 22	-25 char Color,	8	1,749	13,992
	Ethernet*		_	5 005	00.075
MLRB-4L	Reader Board 4 Line 25	char Color, Ethernet [*]	5	5,995	29,975
TMUI-FM5-AB	Multi-unit Indicator Light position*	: - Flush Mount - LED 5	15	925	13,875
TMUI-FM8	Multi-unit Indicator Light	- Flush Mount - LED 8 position MUIs, Ethernet	7	1,695	11,865
	control)	· ,			
TSTB-IN-C	Strobe Light - Indoor Ce	iling Mount	8	99	792
	/SB software module (see VSC software module (se (Subtotal \$118,580	e component allowances)			
		Subtotal (Station)			\$303,168
3.0 Integration (none	defined or not applicable	e to this Quote/Price Lis	st)		
4.0 Services					
Project Manageme	ent				
PMENG-OV	Project & Engineering C	Oversight	1	8,360	8,360
Install Oversight /		votomo)	4	2 750	11 000
CONF01 Installation	Conformance (Zoned Sy	ystems)	4	2,750	11,000
INSTF	Installation		1	277,553	277,553
		Subtotal (Services)			\$296,913
5.0 Totals (Categorize	d by Software, Hardwar	•			¢22.000
		Software Hardware			\$33,906 \$269,262
		Services (excluding any	/ defined in	nstallation)	\$269,262 \$19,360
		Cervices (excluding any		istaliation	ψ19,300

SubTotal (w/o install, maint, options)	\$322,528
Installation	\$277,553
Subtotal	\$600,081
Тах	Assumed no tax
Total (US Dollars)	\$600,081

	nce is not included in the total price & begins after the 1 Year Warranty Pe es not include Server Hardware in Support Maintenance Costs.	riod
MAINT01	Includes annual maintenance for:	
MAINTOT	PrimeAlert Station Software Client Add-ons (for Visual Devices)	4,06
	Locution Station Control Panel(s)	3,63
	Locution Station Enclosure(s)	24
	Radio Interface Unit(s)	45
	Switches (Ack, DayNt, Doorbell, Emergency)	22
	Amplifier(s)	1,26
	Speaker(s) / Volume Control(s)	7,44
	Zone Tracker(s)	1,10
	Reader Board(s)	5,27
	Multi-Unit Indicator(s)	3,08
	LED Lighting (switched)	1,56
	LED Lighting and Controller(s) (ramped)	3,10
	Strobe(s)	9
	Subtotal (Annual Maintenance)	\$31,55