

EXHIBIT A

Page 1 of 3

LPA RX 887 T

Rev. 01/21

Ver. Date 06/18/2021

PID 110376

**PARCEL 20-T1
FRA-161-12.83
TEMPORARY EASEMENT FOR THE PURPOSE OF
PERFORMING THE WORK NECESSARY TO
CONSTRUCT DRIVE AND GRADING
FOR 24 MONTHS FROM DATE OF ENTRY BY THE
CITY OF COLUMBUS, OHIO, A MUNICIPAL CORPORATION**

[Surveyor's description of the premises follows]

Situated in the State of Ohio, County of Franklin, City of Columbus, lying in southeast Quarter Township 4, Township 2 North, Range 18 West, of the United-States Military Lands, part of Lot 2 of the Scioto Land Company Partition as recorded in Deed Book A, Page 194 (destroyed by fire) and re-recorded in Deed Book A, Page 21, part of Lot 48 of Sharon Acres as recorded in Plat Book 20, Page 1, and being part of a 4.000 acre tract conveyed to Northland Gate Senior Housing Limited Partnership, an Ohio limited partnership (hereinafter referred to as "Grantor") by deed of record in Instrument Number 201908290111404 (Franklin County Parcel Number 010-147409-00) (all documents referenced herein are from the Franklin County Recorder's Office), and being more particularly described as follows:

BEGIN FOR REFERENCE at the centerline right-of-way intersection of East Dublin Granville Road (SR 161), (Station 679+77.56) and Maple Canyon Avenue (Station 50+00.00), being referenced by a found iron pin in concrete at centerline Station 685+80.83, (East Dublin Granville Road (SR 161)), 8.31 feet left, which bears South 85° 26' 09" East a distance of 603.59 feet;

Thence North 03° 38' 29" East a distance of 754.98 feet along centerline of Maple Canyon Avenue (width varies) to a point at centerline Station 57+54.98;

Thence North 86° 21' 31" West a distance of 25.00 feet, leaving the centerline across Maple Canyon Avenue to a point at the Grantor's northeasterly corner, on the westerly right-of-way line of Maple Canyon Avenue (width varies) and the southeast corner of a 3.967 acre tract conveyed to Maple Canyon Village Apartments, Limited, an Ohio Limited Partnership by deed of record in Official Record 1719H12, 25.00 feet left of centerline station 57+54.98;

EXHIBIT A

LPA RX 887 T

Rev. 01/21

Thence North $86^{\circ} 30' 30''$ West a distance of 7.00 feet along a line common to the Grantor and the said 3.967 acre tract to a point 32.00 feet left of centerline station 57+54.97';

Thence South $03^{\circ} 38' 29''$ West a distance of 45.97 feet leaving the line common to the Grantor and the said 3.967 acre tract to a point 32.00 feet left of centerline station 57+09.00 and the **TRUE POINT OF BEGINNING** of the Temporary Easement herein described;

Thence the following four (4) courses across the Grantor's 4.000 acre tract;

1. South $03^{\circ} 38' 29''$ West a distance of 57.00 feet to a point 32.00 feet left of centerline station 56+52.00;
2. North $63^{\circ} 44' 20''$ West a distance of 39.00 feet to a point 68.00 feet left of centerline station 56+67.00;
3. North $01^{\circ} 54' 20''$ East a distance of 33.02 feet to a point 69.00 feet left of centerline station 57+00.00;
4. North $79^{\circ} 58' 12''$ East a distance of 38.08 feet to the **TRUE POINT OF BEGINNING**, containing 0.038 acres, more or less, being subject to all easements, restrictions, and right-of-way of record.

This description was prepared by Robert J. Sands, Ohio Professional Survey Number 8053, and is based on a survey conducted by DLZ Ohio, Inc. in 2020 under his direct supervision.

The bearings for this description are based on the Ohio State Plane Coordinate System, South Zone, and reference the North American Datum of 1983 and the 2007 adjustment (NAD83(2007)), with the bearing of Maple Canyon Avenue being North $3^{\circ} 38' 29''$ East.

EXHIBIT A

LPA RX 887 T

Rev. 01/21

Where described, iron pins set are 5/8" rebar, 30" long, with yellow caps stamped "DLZ OHIO INC."

All station and offsets referenced in this description are from the right-of-way centerline of Maple Canyon Avenue as described in the plan known as "IMPROVEMENTS OF SR 161/I71" on file with the Ohio Department of Transportation and the City of Columbus.

Robert J. Sands
Professional Surveyor No. 8053

Date