Page 1 of 1

PARCEL 35-S2 **AMERICAN ADDITION PHASE 4** PERMANENT STORM SEWER EASEMENT

[Surveyor's description of the premises follows]

Situated in the State of Ohio, County of Franklin, City of Columbus, Quarter Township 4, Township 1, Range 18, United States Military District, being on, over and across Lot 122 of that subdivision titled "American Addition", of record in Plat Book 5, Page 448, as conveyed to Bryan Kenyon Bosley and Brianna Bosley by deed of record in Instrument Number 201703310043289 (all references refer to the records of the Recorder's Office, Franklin County, Ohio) being more particularly described as follows:

Beginning, for reference, at the northeasterly corner of said Lot 122 and the southeasterly corner of Lot 123 of said "American Addition", being in the westerly right-of-way line of Sampson Avenue (50 feet wide);

Thence South 04° 06' 54" West, with said westerly right-of-way line, a distance of 15.65 feet to the TRUE POINT OF BEGINNING;

Thence South 04° 06' 54" West, continuing with said westerly right-of-way line, a distance of 13.11 feet to a point;

Thence crossing said Lot 122, the following courses and distances:

North 85° 53' 06" West, a distance of 6.57 feet to a point;

North 04° 06′ 54″ East, a distance of 13.11 feet to a point; and

South 85° 53' 06" East, a distance of 6.57 feet to the TRUE POINT OF BEGINNING, containing 0.002 acre, more or less, of which the present road occupies 0.000 acre and 0.002 acre is part of Franklin County Auditor's Parcel Number 010-126356.

The bearings are based on the Ohio State Plane Coordinate System, South Zone, NAD83 (1986 adjustment). Said bearings originated from a field traverse which was tied (referenced) to said coordinate system by Static GPS observations of Franklin County Engineering Department monuments Frank 43 and Frank 143. The centerline of Joyce Avenue, having a bearing of North 04° 07' 58" East, is designated the "basis of bearing" for this description.

EVANS, MECHWART, HAMBLETON & TILTON, INC.

Brandon R. King Professional Surveyor No. 8772 Date

3776-E

BRK/dif 35S2 0_002 ac 20210310.doc

Ver. Date 05/13/2022