

Bidder Tabulation - Bid #RFQ009983

Purchase of Sewer Combination

Opened October 11, 2018

Bidder Name/Address	Contact Name/#	References	Experience	Warranty	Build Sheet	Literature	Manuals	Attachments	Addenda	C.C. #	Other
The Safety Company	<a href="mailto:dsoukup@mtechcompany.com">dsoukup@mtechcompany.com</a>	Y	Y	Y	Y	Y	Y	Y	Y		Additional Terms and Conditions were submitted, must review and approve prior to any award.
Fyda Freightliner Columbus, Inc.	<a href="mailto:ttolle@fydafreightliner.com">ttolle@fydafreightliner.com</a>	Y	N	Y	Y	Y	N	Y	Y		The experience letter is still needed if awarded.
McClean Company	<a href="mailto:smclean@themccleancompany.com">smclean@themccleancompany.com</a>	Y	Y	Y	Y	Y	N	Y	Y		Additional Terms and Conditions were submitted, must review and approve prior to any award.
Esec Corp	<a href="mailto:timdarr@ameritech.net">timdarr@ameritech.net</a>	Y	N	N	Y	N	N	Y	Y		Bidder provided options. 3.3.1.7 may be non-responsive
Best Equipment	<a href="mailto:debbiecooper@bestequipmentco.com">debbiecooper@bestequipmentco.com</a>	Y	N	N	Y	Y	N	Y	Y		3.3.1.7 may be non-responsive. Bidder did not submit body built sheet 3.3.10.6; Section 3.3.1.8 - Zerk Fittings is not listed within the built sheet of the chassis. ? If a fan or blower type. Need clarification on 3.3.3.1 thru 3.3.3.5 and the comments.
Carly's Repair Services	<a href="mailto:carlysrepairservices@outlook.com">carlysrepairservices@outlook.com</a>	Y	Y	Y	Y	Y	Y	Y	N		Bidder is disqualified, no addenda not attached

Bidder Tabulation - Bid #RFQ009983

Purchase of Sewer Combination

Opened October 11, 2018

Vendor	Type	Line #	Alt.	Total	Product name	Qty	Unit price	Comment
2197	Header		No	\$ 814,209.22				
2197	Line	10	No	\$ 811,209.22	Single Axle Sewer Combination Machine	2.00	\$ 405,604.61	
2197	Line	20	No	\$ 500.00	Cleaning machine operator training	1	\$ 500.00	
2197	Line	30	No	\$ 2,250.00	Manufacturer repair training	3.00	\$ 750.00	
2197	Line	40	No	\$ 250.00	Vehicle Build Inspection	1	\$ 250.00	
4301	Header		No	\$ 777,656.00				
								Complete Vehicle 2020 Freightliner SD114 w/
4301	Line	10	No	\$ 777,656.00	Single Axle Sewer Combination Machine	2	\$ 388,828.00	Vactor 2100i
4301	Line	20	No	\$ -	Cleaning machine operator training	1	\$ -	Included in Above Pricing
4301	Line	30	No	\$ -	Manufacturer repair training	3	\$ -	Included in Above Pricing
4301	Line	40	No	\$ -	Vehicle Build Inspection	1	\$ -	Included in Above Pricing
6445	Header		No	\$ 753,078.28				
6445	Line	10	No	\$ 751,578.28	Single Axle Sewer Combination Machine	2	\$ 375,789.14	
6445	Line	20	No	\$ -	Cleaning machine operator training	1	\$ -	
6445	Line	30	No	\$ -	Manufacturer repair training	3	\$ -	
6445	Line	40	No	\$ 1,500.00	Vehicle Build Inspection	1	\$ 1,500.00	
6602	Header		No	\$ 804,049.68				
6602	Line	10	No	\$ 804,049.68	Single Axle Sewer Combination Machine	2	\$ 402,024.84	
6602	Line	10	Yes	\$ 900,173.08	Gap Vax Body	2	\$ 450,086.54	
6602	Line	20	No	\$ -	Cleaning machine operator training	1	\$ -	included
6602	Line	30	No	\$ -	Manufacturer repair training	3	\$ -	included for 3 techs
6602	Line	40	No	\$ -	Vehicle Build Inspection	1	\$ -	included- 2 trips

Bidder Tabulation - Bid #RFQ009983

Purchase of Sewer Combination

Opened October 11, 2018

Vendor	Type	Line #	Alt.	Total	Product name	Qty	Unit price	Comment
7016	Header		No	\$ 686,853.90				
								3 STAGE FAN ADD \$10,476.00AEROBOOST ADD \$19,377.00824 PD ADD \$33,834.00827 PD ADD \$37,295.00FOR 450 H.P. CHASSIS ADD
7016	Line	10	No	\$ 686,853.90	Single Axle Sewer Combination Machine	2	\$ 343,426.95	\$8,700.00
7016	Line	10	Yes	\$ 704,253.90	Vaccon with 450 H.P.	2	\$ 352,126.95	
7016	Line	20	No	\$ -	Cleaning machine operator training	1	\$ -	
7016	Line	30	No	\$ -	Manufacturer repair training	3	\$ -	
7016	Line	40	No	\$ -	Vehicle Build Inspection	1	\$ -	
24462	Header		No	\$ 787,918.00				
24462	Line	10	No	\$ 787,918.00	Single Axle Sewer Combination Machine	2	\$ 393,959.00	
24462	Line	20	No	\$ -	Cleaning machine operator training	1	\$ -	included
24462	Line	30	No	\$ -	Manufacturer repair training	3	\$ -	included
24462	Line	40	No	\$ -	Vehicle Build Inspection	1	\$ -	included