## EXHIBIT A

LPA RX 887 T

Ver. Date 07/29/2014

Page 1 of 2 Rev. 07/09

PID 94913

## PARCEL 11-T FRA-GEORGESVILLE/HOLT IMPROVEMENTS TEMPORARY EASEMENT FOR THE PURPOSE OF PERFORMING THE WORK NECESSARY TO COMPLETE GRADING AND DRIVE CONSTRUCTION FOR 24 MONTHS FROM DATE OF ENTRY BY THE CITY OF COLUMBUS, FRANKLIN COUNTY, OHIO

## [Surveyor's description of the premises follows]

Situated in the City of Columbus, County of Franklin, State of Ohio, Virginia Military Survey No. 1462 and being part of a tract in the name of Fifth Third Bank, an Ohio Banking Corporation (hereinafter known as the "Grantor") as recorded in Instrument No. 200503020037918 of said county records.

Being a parcel of land lying on the left side of the centerline of right of way of Holt Road as shown on the centerline plat of FRA-Georgesville/Holt Improvements as recorded in Plat Book \_\_\_\_\_\_, Page \_\_\_\_\_ of the records of Franklin County and being further described as follows:

Commencing, for reference, at 5/8" rebar (found) at the northeast corner of Lot 18 as shown on Georgesville Square Subdivision and Dedication of Holt Road, recorded in Plat Book 87, Page 11, said corner being 50.00 feet left of station 43+21.13; Thence, along the northerly line of said Holt Road, North 76 degrees 01 minutes 30 seconds East, a distance of 50.18 feet to the centerline of Holt Road at station 43+16.96; Thence, southeasterly, along said centerline and the arc of a curve deflecting to the left, having a central angle of 23 degrees 35 minutes 05 seconds, a radius of 850.00 feet, and a chord that bears South 30 degrees 47 minutes 55 seconds East, a distance of 347.42 feet to a point at station 39+67.07; Thence, continuing along said centerline, South 42 degrees 35 minutes 23 seconds East, a distance of 952.99 feet to a point at station 30+14.08; Thence, across the southerly existing right of way line of Holt Road, South 47 degrees 24 minutes 37 seconds West, a distance of 50.00 feet to the southeasterly corner of the grantor's tract and the northeasterly corner of a 1.508 acre tract in the name of Holt Run Center, LLC, an Ohio Limited Liability Company, as recorded in Instrument No. 200506270124194, said corner being on the southerly existing right of way line of Holt Road, south esoutherly existing right of way line of the easement herein described;

Thence, along the grantor's southeasterly property line and the northwesterly property line of said Holt Run Center tract, South 47 degrees 11 minutes 41 seconds West, a distance of 50.00 feet to a point 100.00 feet left of station 30+13.89;

Thence, across the grantor's tract, for the following five (5) calls:

- 1. North 42 degrees 35 minutes 23 seconds West, a distance of 56.11 feet to a point 100.00 feet left of station 30+70.00;
- 2. North 47 degrees 24 minutes 37 seconds East, a distance of 40.00 feet to a point 60.00 feet left of station 30+70.00;

## EXHIBIT A

LPA RX 887 T

Page 2 of 2 Rev. 07/09

- 3. North 16 degrees 01 minutes 29 seconds West, a distance of 11.18 feet to a point 55.00 feet left of station 30+80.00;
- 4. North 42 degrees 35 minutes 23 seconds West, a distance of 27.00 feet to a point 55.00 feet left of station 31+07.00;
- 5. North 47 degrees 24 minutes 37 seconds East, a distance of 5.00 feet to a point on the southerly existing right of way line of Holt Road, 50.00 feet left of station 31+07.00;

Thence, along the southerly existing right of way line of Holt Road, South 42 degrees 35 minutes 23 seconds East, a distance of 92.92 feet to the **Point of Beginning**, containing 0.069 acres, of which the present road occupies 0.000 acres, and is contained within Franklin County Auditor's Permanent Parcel No. 010-274827.

The bearings for this description are based on the centerline of Automall Drive being North 14 degrees 31 minutes 14 seconds West, as derived from Ohio State Plane Coordinate System, South Zone, NAD83(2011), as resolved by GPS observations using the Ohio Department of Transportation Virtual Reference System network.

All iron pins set are 5/8" x 30" rebar with cap stamped "2LMN".

This description was prepared and reviewed under the supervision of Richard F. Mathias, Professional Surveyor No. 7798 from a survey conducted for the City of Columbus, Ohio in October, 2013.

Richard F. Mathias, P.S. Professional Surveyor No. 7798 Date