

SUB-CONTRACTOR WORK IDENTIFICATION FORM

CIP 611010-100000 - Holt Ave/Somersworth Dr Stormwater System Improvements							
Contractor and Subcontractor CCCN, Scope and Funding Summary				DATE:	6/15/2011		Ordinance# 1033-2011
Name/ Address	Prime or SubCont	Contact Information	C.C. #/ Expires	Firm Type	Type of Work	Contract \$ Amount/%	Contract Scope
GS&P/OH, Inc. (Gresham, Smith & Partners) 155 E. Broad St, Suite 900 Columbus, Ohio 43215	Prime	David S. Pyzoha, PE Senior Associate 614-221-0678 (office) 937-478-7335 (cell) david_pyzoha@gspnet.com	62-1736493 02/05/12 Active	MAJ	Civil Engineering and Infrastructure Design	\$ 144,306.34 62.908%	Project Management, Hydrologic/Hydraulic Analysis, Construction Documents, Public Meetings, Water Main Design, Green BMPs, SWPPP, Bidding QA/QC, Record Drawings
Dynotec, Inc. 2931 E. Dublin-Granville Rd. Suite 200 Columbus, Ohio 43231	Subcont.	Joseph Bolzenius, PE, PS Surveyor Manager 614-330-1099 (office) 614-8807324 (fax) jbolzenius@dynotecinc.com	31-1319961 05/02/13 Active	MBE	Civil Engineering and Surveying Services	\$ 41,761.25 18.205%	Topographic Surveying and Easements
DHDC, Inc. 2390 Advanced Business Center Columbus, OH 43228	Subcont.	Savvas P. Sophocleous Project Coordinator 614-527-7656 (office) (614)880-7324 (fax) info@dhdinc.com	31-1227692 03/01/12 Active	MBE	Geotechnical Engineering, Laboratory Testing, Surveying, Construction Inspection	\$ 27,636.43 12.048%	Geotechnical Investigations and Utility Locates
Dreier & Maller, Inc. 6508 Taylor Rd. SW Reynoldsburg, OH 43068	Subcont.	Steve Maller Principal/Owner 614-575-0065 614-205-6990 (cell) info@dreierandmaller.com	34-1681027 04/06/12 Active	MAJ	Sewer System Inspection	\$ 15,690.00 6.840%	Storm Sewer CCTV and Cleaning
						\$229,394.02	
						100.00%	
					Majority	69.75%	
					MBE	30.25%	
					FBE	0.00%	