

**EXHIBIT A**

Page 1 of 2

LPA RX 887 T

Rev. 07/09

Ver. Date 07/29/2014

PID 94913

**PARCEL 10-T2  
FRA-GEORGESVILLE/HOLT IMPROVEMENTS  
TEMPORARY EASEMENT FOR THE PURPOSE OF  
PERFORMING THE WORK NECESSARY TO  
COMPLETE GRADING AND DRIVE CONSTRUCTION  
FOR 24 MONTHS FROM DATE OF ENTRY BY THE  
CITY OF COLUMBUS, FRANKLIN COUNTY, OHIO**

[Surveyor's description of the premises follows]

---

Situated in the City of Columbus, County of Franklin, State of Ohio, Virginia Military Survey No. 1462 and being part of a tract in the name of Holt Run Center, LLC, an Ohio Limited Liability Company (hereinafter known as the "Grantor") as recorded in Instrument No. 200506270124194 of said county records.

Being a parcel of land lying on the left side of the centerline of right of way of Holt Road as shown on the centerline plat of FRA-Georgesville/Holt Improvements as recorded in Plat Book \_\_\_\_\_, Page \_\_\_\_\_ of the records of Franklin County and being further described as follows:

Commencing, for reference, at 5/8" rebar (found) at the northeast corner of Lot 18 as shown on Georgesville Square Subdivision and Dedication of Holt Road, recorded in Plat Book 87, Page 11, said corner being 50.00 feet left of station 43+21.13; Thence, along the northerly line of said Holt Road, North 76 degrees 01 minutes 30 seconds East, a distance of 50.18 feet to the centerline of Holt Road at station 43+16.96; Thence, southeasterly, along said centerline and the arc of a curve deflecting to the left, having a central angle of 23 degrees 35 minutes 05 seconds, a radius of 850.00 feet, and a chord that bears South 30 degrees 47 minutes 55 seconds East, a distance of 347.42 feet to a point at station 39+67.07; Thence, continuing along said centerline, South 42 degrees 35 minutes 23 seconds East, a distance of 952.99 feet to a point at station 30+14.08; Thence, across the southerly existing right of way of Holt Road, South 47 degrees 24 minutes 37 seconds West, a distance of 50.00 feet to the northeasterly corner of the grantor's tract and the southeasterly corner of a 1.357 acre tract in the name of Fifth Third Bank, an Ohio Banking Corporation, as recorded in Instrument No. 200503020037918, said corner being on the southerly existing right of way line of Holt Road, 50.00 feet left of station 30+14.08, and also being the **Point of Beginning** of the easement herein described;

Thence, along said existing right of way line of Holt Road, South 42 degrees 35 minutes 23 seconds East, a distance of 36.08 feet to a point 50.00 feet left of station 29+78.00;

Thence, across the grantor's tract, for the following five (5) calls:

1. South 47 degrees 24 minutes 37 seconds West, a distance of 5.00 feet to a point 55.00 feet left of station 29+78.00;
2. North 42 degrees 35 minutes 23 seconds West, a distance of 20.00 feet to a point 55.00 feet left of station 29+98.00;

**EXHIBIT A**

LPA RX 887 T

Rev. 07/09

3. South 78 degrees 22 minutes 26 seconds West, a distance of 23.32 feet to a point 75.00 feet left of station 30+10.00;
4. South 47 degrees 24 minutes 37 seconds West, a distance of 25.00 feet to a point 100.00 feet left of station 30+10.00;
5. North 42 degrees 35 minutes 23 seconds West, a distance of 3.89 feet to a point on the grantor's northwesterly line and the southeasterly line of said Fifth Third Bank tract, 100.00 feet left of station 30+13.89;

Thence, along the grantor's northwesterly line, North 47 degrees 11 minutes 41 seconds East, a distance of 50.00 feet to the **Point of Beginning**, containing 0.011 acres, of which the present road occupies 0.000 acres, and is contained within Franklin County Auditor's Permanent Parcel No. 010-276416.

The bearings for this description are based on the centerline of Automall Drive being North 14 degrees 31 minutes 14 seconds West, as derived from Ohio State Plane Coordinate System, South Zone, NAD83(2011), as resolved by GPS observations using the Ohio Department of Transportation Virtual Reference System network.

All iron pins set are 5/8" x 30" rebar with cap stamped "2LMN".

This description was prepared and reviewed under the supervision of Richard F. Mathias, Professional Surveyor No. 7798 from a survey conducted for the City of Columbus, Ohio in October, 2013.

---

Richard F. Mathias, P.S.  
Professional Surveyor No. 7798

Date