EXHIBIT A

Page 1 of 2

RX 286 T Rev. 06/09

Ver. Date 04/15/13 PID 17585

PARCEL 68-T FRA-C.R. 61-1.10 TEMPORARY EASEMENT FOR THE PURPOSE OF PERFORMING THE WORK NECESSARY TO REONSTRUCT A DRIVE AND GRADE SLOPES FOR 24 MONTHS FROM DATE OF ENTRY BY THE STATE OF OHIO, DEPARTMENT OF TRANSPORTATION

[Surveyor's description of the premises follows]

Situated in the State of Ohio, County of Franklin, City of Columbus, located in Farm Lot 15 of Flavel Tuller's Survey of Quarter Township 1, Township 2 North, Range 19 West, United States Military Lands, as recorded in Plat Book 3, Page 60, and being a part of Lot 21 of the Barbary Ridge Subdivision as recorded in Plat Book 84, Page 52, as conveyed to R.E.S., Inc., by deed of record in Instrument Number 199906160153633, all records of the Recorder's Office, Franklin County, Ohio, and being more particularly described as follows:

Being a parcel of land located on the left side of the Plat of the Centerline of Right-of-Way of FRA-C.R. 61-1.10, as recorded in Plat Book_____, Page_____;

Beginning at a 1" iron pipe found at a southeast corner of said Lot 21, being 40.00 feet left of Hard Road centerline station 150+23.26;

Thence North 87 degrees 38 minutes 42 seconds West, a distance of 97.13 feet along the southerly line of said Lot 21, and along the existing northerly Right-of-Way line of Hard Road, to an iron pin set being 40.00 feet left of Hard Road centerline station 149+26.13;

Thence along the arc of a curve to the right for 47.12 feet across said Lot 21, and along the proposed northerly Right-of-Way line of Hard Road, having a radius of 30.00 feet, a central angle of 90 degrees 00 minutes 00 seconds, a chord bearing of North 42 degrees 38 minutes 42 seconds West, a chord distance of 42.43 feet to an iron pin set being 70.00 feet left of Hard Road centerline station 148+96.13;

Thence North 02 degrees 21 minutes 18 seconds East, a distance of 51.00 feet along the existing easterly Right-of-Way line of Tripoli Court, and along the westerly line of said Lot 21, to a 1" iron pipe found marking the northwest corner of said Lot 21, being 121.00 feet left of Hard Road centerline station 148+96.13;

Rev. 06/09

Thence South 87 degrees 38 minutes 42 seconds East, a distance of 8.87 feet along the northerly line of said Lot 21, to a point being 121.00 feet left of Hard Road centerline station 149+05.00;

Thence South 11 degrees 27 minutes 36 seconds East, a distance of 62.82 feet across said Lot 21, to a point being 60.00 feet left of Hard Road centerline station 149+20.00;

Thence South 61 degrees 04 minutes 48 seconds East, a distance of 22.36 feet across said Lot 21, to a point being 50.00 feet left of Hard Road centerline station 149+40.00;

Thence South 87 degrees 38 minutes 42 seconds East, a distance of 83.25 feet across said Lot 21, to a point in the easterly line of said Lot 21, being 50.00 feet left of Hard Road centerline station 150+23.25;

Thence South 02 degrees 20 minutes 11 seconds West, a distance of 10.00 feet along the easterly line of said Lot 21 to the **Point of Beginning**, containing 0.055 acres, more or less;

Of the above described area, 0.055 acres is contained within the Franklin County Auditor's Parcel 610-235380.

The bearing datum of the afore-described parcel is based upon the Ohio State Plane Coordinate System, South Zone, NAD 1983 (1986 Adjustment), as measured using G.P.S. methods through the Franklin County Engineer's stations FRANK 74, FRANK 174, FCGS 7772, FCGS 6651, FCGS 2232, and FRANK 2218 RESET.

This description was based upon an actual field survey of Hard Road by Stantec Consulting Services, Inc., in October and November of 2010, under the direction of Tim A. Baker, Registered Surveyor Number 7818.

Iron Pins Set are 3/4 inches in diameter by 30 inches long with a 2 inch aluminum cap placed on top bearing the name "ODOT R/W" and "STANTEC".

Grantor Claims title by instrument of record in Instrument Number 199906160153633, of the Recorder's Office, Franklin County, Ohio.

Registered Surveyor No. 7818