

EXHIBIT A

Page 1 of 2

RX 250 WD

Rev. 06/09

Ver. Date 04/15/13

PID 17585

**PARCEL 30-WD
FRA-C.R. 61-1.10
ALL RIGHT, TITLE AND INTEREST IN FEE SIMPLE
IN THE FOLLOWING DESCRIBED PROPERTY
WITHOUT LIMITATION OF EXISTING ACCESS RIGHTS**

Grantor/Owner, for himself and his heirs, executors, administrators, successors and assigns, reserves all existing rights of ingress and egress to and from any residual area (as used herein, the expression "Grantor/Owner" includes the plural, and words in the masculine include the feminine or neuter).

[Surveyor's description of the premises follows]

Situated in the State of Ohio, County of Franklin, City of Columbus, located in Farm Lot 18 of Flavel Tuller's Survey of Quarter Township 1, Township 2 North, Range 19 West, United States Military Lands, as recorded in Plat Book 3, Page 60, and being a part of Lot 956 of the Olde Sawmill Section Nine Subdivision as recorded in Plat Book 60, Page 64, as conveyed to Vasily N. Mikhalyuk and Anna S. Mikhalyuk by deeds of record in Instrument Number 199708290082129 and Instrument Number 200404290096795, all records of the Recorder's Office, Franklin County, Ohio, and being more particularly described as follows:

Being a parcel of land located on the left side of the Plat of the Centerline of Right-of-Way of FRA-C.R. 61-1.10, as recorded in Plat Book ____, Page ____;

Beginning for Reference at a 1" iron pipe found marking the southwest corner of said Lot 956, being 40.00 feet left of Hard Road centerline station 126+17.96;

Thence South 87 degrees 39 minutes 05 seconds East, a distance of 90.00 feet along the southerly line of said Lot 956, and along the existing northerly Right-of-Way line of Hard Road, to an iron pin set being 40.00 feet left of Hard Road centerline station 127+07.96, and being the **Point of True Beginning**;

Thence North 55 degrees 28 minutes 43 seconds East, a distance of 50.00 feet across said Lot 956 to an iron pin set at the intersection with the existing westerly Right-of-Way line of Stanburn Road, being 70.00 feet left of Hard Road centerline station 127+47.96;

EXHIBIT A

RX 250 WD

Rev. 06/09

Thence South 02 degrees 20 minutes 55 seconds West, a distance of 10.00 feet along the existing westerly Right-of-Way line of Stanburn Road, and along the easterly line of said Lot 956 to a point being 60.00 feet left of Hard Road centerline station 127+47.96;

Thence along the arc of a curve to the right for 31.42 feet along the southeasterly line of said Lot 956, and along the existing northerly Right-of-Way line of Hard Road, having a radius of 20.00 feet, a central angle of 90 degrees 00 minutes 00 seconds, a chord bearing of South 47 degrees 20 minutes 55 seconds West, a chord distance of 28.28 feet to a point being 40.00 feet left of Hard Road centerline station 127+27.96;

Thence North 87 degrees 39 minutes 05 seconds West, a distance of 20.00 feet along the southerly line of said Lot 956, and along the existing northerly Right-of-Way line of Hard Road, to the **Point of True Beginning**, containing 0.012 acres, more or less;

Of the above described area, 0.012 acres is contained within the Franklin County Auditor's Parcel 590-195040.

The bearing of South 87 degrees 39 minutes 05 seconds East for the centerline of Hard Road is based upon the Ohio State Plane Coordinate System, South Zone, NAD 1983 (1986 Adjustment), as measured using G.P.S. methods through the Franklin County Engineer's stations FRANK 74, FRANK 174, FCGS 7772, FCGS 6651, FCGS 2232, and FRANK 2218 RESET.

This description was based upon an actual field survey of Hard Road by Stantec Consulting Services, Inc., in October and November of 2010, under the direction of Tim A. Baker, Registered Surveyor Number 7818.

Iron Pins Set are 3/4 inches in diameter by 30 inches long with a 2 inch aluminum cap placed on top bearing the name "ODOT R/W" and "STANTEC".

Grantor Claims title by instrument of record in Instrument Number 199708290082129 and Instrument Number 200404290096795, of the Recorder's Office, Franklin County, Ohio.

STANTEC CONSULTING SERVICES, INC.

Registered Surveyor No. 7818