


Group B CC15608 Griggs & O'Shaughnessy Reservoirs









Group B CC15608 Griggs & O'Shaughnessy

Basin

Swale











Group B CC15608 Hoover Reservoir





# Group B CC15608 Hoover Reservoir



- Basin
- Swale



# DPU DashBoard Map



Group B  
CC13366 Idlewild Drive

CIP 073  
Idlewild Drive  
Stormwater System Improvements  
2 Basins / Wetlands









# American Addition Phase 1

Group B  
E2639 - 4 Rain Gardens





# Crawford Farms - Stormwater Retrofit









# Watershed Roadway Improvement Part 3

Group B  
CC17192 - Plan Page 9  
2-BioBasins  
Small segment of basin was  
not built, replaced with bushes,  
see note on plan 9.




1- Basin B

1- Basin A

Riverside Drive

Stratford Drive






# Watershed Roadway Improvements - Part 3

Group B  
CC17192 - Plan Page 11  
1-BioBasin inside fence area  
at the maintenance office.

Note: Item 1 - Basin C is located near CC15608-Basin Item 2

Griggs Dam






# Watershed Roadway Improvements Part 3

Group B  
CC17192-Plan Page 14  
2-Trench Drains discharge to  
existing basins CC15608

2 Trench Drains









# CC16258 Dublin Road Water Plant Treatment Capacity Increase

4-Bio-Swales A, B, C & D




1-Central Bio-Rt Basin  
Pending

1-Bio-Retention Basin A







Group B

CC16422  
Dublin Road Water Plant  
No. 3  
1 Bio-Basin

