



Graffiti on deteriorated piping on 010-180602

A photograph showing a metal shopping cart lying on its side in a grassy, wooded area. The cart is silver and has a black label on its side. It is positioned near a large tree with dense green foliage. The ground is covered in grass and some fallen leaves. In the background, there are more trees and a small stream or ditch.

010180602 homeless camping area



Extensive graffiti found underneath I-670 adjacent to
010-066303






010-066303 Environmental monitoring
pipe

**010-180602 broken deteriorated old
foundation**






010-180602 broken, deteriorated, foundation wall






010-180602 broken deteriorated foundation wall





010-066303 Environmental monitoring pipe



A photograph of an environmental monitoring well in a wooded area. The well is a yellow, cylindrical pipe protruding from the ground, surrounded by dense green foliage and trees. The ground is covered with fallen leaves. The text "010-180602 Environmental monitoring well" is overlaid in white at the bottom left, and a black rectangular box is at the bottom right.

010-180602 Environmental monitoring well



010-180602 Enviornmental monitoring well

