

**EXHIBIT A**

Page 1 of 2

RX 250 WD

Rev. 06/09

Ver. Date 04/15/13

PID 17585

**PARCEL 31-WD  
FRA-C.R. 61-1.10  
ALL RIGHT, TITLE AND INTEREST IN FEE SIMPLE  
IN THE FOLLOWING DESCRIBED PROPERTY  
WITHOUT LIMITATION OF EXISTING ACCESS RIGHTS**

Grantor/Owner, for himself and his heirs, executors, administrators, successors and assigns, reserves all existing rights of ingress and egress to and from any residual area (as used herein, the expression "Grantor/Owner" includes the plural, and words in the masculine include the feminine or neuter).

[Surveyor's description of the premises follows]

Situated in the State of Ohio, County of Franklin, City of Columbus, located in Farm Lot 18 of Flavel Tuller's Survey of Quarter Township 1, Township 2 North, Range 19 West, United States Military Lands, as recorded in Plat Book 3, Page 60, and being a part of Lot 957 of the Olde Sawmill Section Nine Subdivision as recorded in Plat Book 60, Page 64, as conveyed to Jodi L. Bush by deed of record in Instrument Number 200312150394552, all records of the Recorder's Office, Franklin County, Ohio, and being more particularly described as follows:

Being a parcel of land located on the left side of the Plat of the Centerline of Right-of-Way of FRA-C.R. 61-1.10, as recorded in Plat Book\_\_\_\_, Page\_\_\_\_;

**Beginning** at a 5/8" iron pin found at a southwest corner of said Lot 957, being 60.00 feet left of Hard Road centerline station 128+07.96;

Thence North 02 degrees 20 minutes 55 seconds East, a distance of 10.00 feet along the existing easterly Right-of-Way line of Stanburn Road, and along the westerly line of said Lot 957, to an iron pin set at the intersection with the proposed northerly Right-of-Way line of Hard Road, being 70.00 feet left of Hard Road centerline station 128+07.96;

Thence South 50 degrees 46 minutes 54 seconds East, a distance of 50.00 feet across said Lot 957 to an iron pin set at the intersection with the existing northerly Right-of-Way line of Hard Road, being 40.00 feet left of Hard Road centerline station 128+47.96;

Thence North 87 degrees 39 minutes 05 seconds West, a distance of 20.00 feet along the southerly line of said Lot 957, and along the existing northerly Right-of-Way line of Hard Road, to a point being 40.00 feet left of Hard Road centerline station 128+27.96;

**EXHIBIT A**

Page 2 of 2

RX 250 WD

Rev. 06/09

Thence along the arc of a curve to the right for 31.42 feet along the southwesterly line of said Lot 957, and along the existing northerly Right-of-Way line of Hard Road, having a radius of 20.00 feet, a central angle of 90 degrees 00 minutes 00 seconds, a chord bearing of North 42 degrees 39 minutes 05 seconds West, a chord distance of 28.28 feet to the **Point of Beginning**, containing 0.012 acres, more or less;

Of the above described area, 0.012 acres is contained within the Franklin County Auditor's Parcel 590-195041.

The bearing of South 87 degrees 39 minutes 05 seconds East for the centerline of Hard Road is based upon the Ohio State Plane Coordinate System, South Zone, NAD 1983 (1986 Adjustment), as measured using G.P.S. methods through the Franklin County Engineer's stations FRANK 74, FRANK 174, FCGS 7772, FCGS 6651, FCGS 2232, and FRANK 2218 RESET.

This description was based upon an actual field survey of Hard Road by Stantec Consulting Services, Inc., in October and November of 2010, under the direction of Tim A. Baker, Registered Surveyor Number 7818.

Iron Pins Set are 3/4 inches in diameter by 30 inches long with a 2 inch aluminum cap placed on top bearing the name "ODOT R/W" and "STANTEC".

Grantor Claims title by instrument of record in Instrument Number 200312150394552, of the Recorder's Office, Franklin County, Ohio.

**STANTEC CONSULTING SERVICES, INC.**

---

Registered Surveyor No. 7818