

EXHIBIT A

Page 1 of 2

RX 250 WD

Rev. 06/09

Ver. Date 04/15/13

PID 17585

**PARCEL 26-WD
FRA-C.R. 61-1.10
ALL RIGHT, TITLE AND INTEREST IN FEE SIMPLE
IN THE FOLLOWING DESCRIBED PROPERTY
WITHOUT LIMITATION OF EXISTING ACCESS RIGHTS**

Grantor/Owner, for himself and his heirs, executors, administrators, successors and assigns, reserves all existing rights of ingress and egress to and from any residual area (as used herein, the expression "Grantor/Owner" includes the plural, and words in the masculine include the feminine or neuter).

[Surveyor's description of the premises follows]

Situated in the State of Ohio, County of Franklin, City of Columbus, located in Farm Lot 17 of Flavel Tuller's Survey of Quarter Township 1, Township 2 North, Range 19 West, United States Military Lands, as recorded in Plat Book 3, Page 60, and being a part of Lot 430 of the Summerwood Section No. 4 Part Three Subdivision as recorded in Plat Book 60, Page 63, as conveyed to Brian P. Mieczkowski and Brooklynn D. Mieczkowski by deed of record in Instrument Number 201005040053900, all records of the Recorder's Office, Franklin County, Ohio, and being more particularly described as follows:

Being a parcel of land located on the right side of the Plat of the Centerline of Right-of-Way of FRA-C.R. 61-1.10, as recorded in Plat Book ____, Page ____;

Beginning at a 1/2" rebar found marking a northeast corner of said Lot 430, being 40.00 feet right of Hard Road centerline station 127+28.32;

Thence along the arc of a curve to the right for 31.42 feet along the northeasterly line of said Lot 430, and along the existing southerly Right-of-Way line of Hard Road, having a radius of 20.00 feet, a central angle of 90 degrees 00 minutes 00 seconds, a chord bearing of South 42 degrees 39 minutes 05 seconds East, a chord distance of 28.28 feet to a 1/2" rebar found being 60.00 feet right of Hard Road centerline station 127+48.32;

Thence South 02 degrees 20 minutes 55 seconds West, a distance of 10.00 feet along the existing westerly Right-of-Way line of Stanburn Road, and along the easterly line of said Lot 430, to an iron pin set being 70.00 feet right of Hard Road centerline station 127+48.32;

EXHIBIT A

Page 2 of 2

RX 250 WD

Rev. 06/09

Thence North 50 degrees 46 minutes 54 seconds West, a distance of 50.00 feet across said Lot 430 to an iron pin set at the intersection with the existing southerly Right-of-Way line of Hard Road, being 40.00 feet right of Hard Road centerline station 127+08.32;

Thence South 87 degrees 39 minutes 05 seconds East, a distance of 20.00 feet along the northerly line of said Lot 430, and along the existing southerly Right-of-Way line of Hard Road, to the **Point of Beginning**, containing 0.012 acres, more or less;

Of the above described area, 0.012 acres is contained within the Franklin County Auditor's Parcel 590-195114.

The bearing of South 87 degrees 39 minutes 05 seconds East for the centerline of Hard Road is based upon the Ohio State Plane Coordinate System, South Zone, NAD 1983 (1986 Adjustment), as measured using G.P.S. methods through the Franklin County Engineer's stations FRANK 74, FRANK 174, FCGS 7772, FCGS 6651, FCGS 2232, and FRANK 2218 RESET.

This description was based upon an actual field survey of Hard Road by Stantec Consulting Services, Inc., in October and November of 2010, under the direction of Tim A. Baker, Registered Surveyor Number 7818.

Iron Pins Set are 3/4 inches in diameter by 30 inches long with a 2 inch aluminum cap placed on top bearing the name "ODOT R/W" and "STANTEC".

Grantor Claims title by instrument of record in Instrument Number 201005040053900, of the Recorder's Office, Franklin County, Ohio.

STANTEC CONSULTING SERVICES, INC.

Registered Surveyor No. 7818