

**SCHEDULE 2A-1
SUBCONTRACTOR WORK IDENTIFICATION**

Project Name: West Side Trunk Large Diameter Sewer Condition Assessment						Dept. of Public Utilities		Date: 10/31/2017		
Project Number: 650725-100010						Division:				
City Project Manager: Jehan Alkhayri						Contract Amt or Mod (\$):				
PM Phone #: (614) 645-5423						\$981,578.59				
Prime Contractor/Consultant: Burgess & Niple, Inc.						Ordinance #: 3003-2017				Contract Duration: 12 MOS
Contractor and Subcontractor CCCN, Scope, and Funding Summary										
	Name / Address	Prime or Sub	Contact Information	C.C.# / Expires	DAX Vendor #	Firm Type	Contract or Mod Scope	Contract or Mod Amount & %		
1	Burgess & Niple, Inc.	Prime	John Swartzbaugh, PE	31-0885550	004425	Maj	Project Management,	\$ 354,669.64		
	5085 Reed Road		John.Swartzbaugh@burgessniple.com	2/4/2018			Sewer Condition Assessment	36.1%		
	Columbus, Ohio 43220		O-(614) 459-2050				Manhole Inspections,			
			M - (614) 989-7759				Technical Memo			
2	CDM Smith	Sub	John Schroeder, PE	04-2473650	000180	Maj	Manhole Inspections	\$ 73,837.22		
	445 Hutchinson Ave. Suite 820		SchroederJP@cdmsmith.com	11/15/2018			Sewer Condition Assessment	7.5%		
	Columbus OH 43235		(614) 847-8340				Technical Memo			
3	Resource International, Inc.	Sub	Jim Turner	31-0669793	004197	FBE	Field Survey, CCTV Oversight,	\$ 73,072.09		
	6350 Presidential Gateway		614.823.4949	3/24/2018			Manhole Inspections	7.4%		
	Columbus, Ohio 43231		jimt@resourceinternational.com							
5	Hydromax USA	Sub	Jeffrey Graham	20-0602448	000958	Maj	Video Recording	\$ 480,000.00		
	11492 Bluegrass Parkway, Suite 106		jeff.graham@hydromaxusa.com	11/17/2017			Sonar Inspections	48.9%		
	Louisville, KY 40299		(502) 548-8965				Man Entry Inspections			
6										
7										
8										
DPU Fiscal Revised 8/9/2016			Approved:				TOTAL CONTRACT or Mod AMOUNT		981,578.95	
			Date:				Total Percentage		100.0%	